

N32G401 Series Errata Sheet V1.0.0



Contents

1	Erra	Errata List1					
2	Power Control (PWR)						
	2.1	2.1 Cannot reset from DEBUG STOP2 mode by pressing NRST button					
3	Time	Timer (TIM)					
	3.1	TIM1/2/3/4/5/8 cannot generate compare events under certain circumstances	3				
4	Serial Peripheral Interface (SPI)						
	4.1	I2S interface	4				
	4.1.1	PCM long frame mode	4				
5	Real	Time Clock (RTC)	5				
	5.1	RTC automatic wake up	5				
	5.2	The RTC wakeup event is generated before the chip enters STANDBY and cannot wake up	5				
	5.3	The RTC calendar function cannot be initialized multiple times within 1 second	5				
	5.4	The RTC triggers the TISOVF flag by mistake	6				
	5.5	The shift operation of the RTC on the subsecond causes the current wake-up time is inaccurate	6				
	5.6	RTC_DATE register lock	6				
6	GPIC	O and AFIO	7				
	6.1	IO appeared burr during power-on	7				
7 Controller Area Network (CAN)错误!未							
	7.1	CAN active error错误!未定义书签。					
8	Marl	Marking information					
9	Version history9						
10 Notice							



1 Errata List

				Chip version	
	Errata link		Version C	Version D	
Section 2: Power Control (PWR)	Section 2.1: Cannot reset from DEBUG STOP2 mode by pressing NRST button		•		
Section 3: Timer (TIM)	Section 3.1: TIM1/2/3/4/5/8 cannot generate compare events under certain circumstances		•	•	
Section 4: Serial Peripheral Interface (SPI)	Section 4.1: I2S interface	Section 4.1.1: PCM long frame mode	•	•	
	Section 5.1: RTC automatic wake up		•	•	
	Section 5.2: The RTC wakeup event is generated before the chip enters STANDBY and cannot wake up		•		
	Section 5.3: The RTC calendar function cannot be initialized multiple times within 1 second		•		
Section 5: Real Time Clock (RTC)	Section 5.4: The RTC triggers the TISOVF flag by mistake		•		
	Section 5.5: The shift operation of the RTC on the subsecond causes the current wake-up time is inaccurate		•	•	
	Section 5.6: RTC_DATE register lock		•	•	
Section 6: GPIO and AFIO	ion 6: GPIO and AFIO Section 6.1: IO appeared burr during power-on		•		

Table 1-1 Errata overview



2 Power Control (PWR)

2.1 Cannot reset from DEBUG STOP2 mode by pressing NRST button

Description

When the DBG_CTRL.STOP bit is set to 1 and the chip enters the STOP2 mode, the chip cannot be reset by pressing the NRST button.

Resolution

Before the chip enters STOP2 mode, clear the DBG_CTRL.STOP bit to 0.



3 Timer (TIM)

3.1 TIM1/2/3/4/5/8 cannot generate compare events under certain

circumstances

Description

In edge-aligned mode, in up-counting PWM1 mode, when the current PWM cycle CCDATx shadow register >= AR value, the shadow register value of CCDATx in the next PWM cycle is 0. At the moment when the PWM cycle counter is 0, although the count value = CCDATx shadow register value = 0 and OCxREF = 0, but still no compare event is generated.

Resolution

If it is not required that "the comparison event is generated at the time when the count value = the shadow register of the comparison value =0", the comparison event generated through another channel can replace the comparison event that is not generated.



4 Serial Peripheral Interface (SPI)

4.1 I2S interface

4.1.1 PCM long frame mode

Description

When I2S works in master mode, PCM long frame mode, and the data format is "32bit" or "16bit extended to 32bit", the WS signal is one cycle per 16bit instead of 32bit.

Resolution

When I2S works in master mode and the long frame mode must be used, the 16bit data mode should be used.



5 Real Time Clock (RTC)

5.1 RTC automatic wake up

Description

After the RTC calendar setting is completed, configure the automatic wake-up function. The time from enabling automatic wake-up to the first wake-up is smaller than the wake-up automatic reload value, and the subsequent automatic wake-up time is normal.

Resolution

Ignore the first wakeup.

5.2 The RTC wakeup event is generated before the chip enters STANDBY

and cannot wake up

Description

Before the chip enters STANDBY mode, if an RTC wakeup event occurs, the chip will not wake up after entering STANDBY mode.

Resolution

None.

5.3 The RTC calendar function cannot be initialized multiple times within

1 second

Description

The RTC calendar function is initialized multiple times within 1 second, so that the RTC alarm clock interrupt cannot be generated.

Resolution

The interval between two initializations of the RTC calendar function is more than 1 second.



5.4 The RTC triggers the TISOVF flag by mistake

Description

When the system wakes up from STANDBY mode or the IWDG times out and the system reset, the RTC may triggers the TISOVF flag by mistake probability.

Resolution

Before entering STANDBY mode or IWDG time out, when the SHOPF flag is 0, configure

RTC_SCTRL.SUBF[14:0] register for the first time, and SHOPF flag will set 1. When SHOPF flag is 0 again,

configure RTC_SCTRL.SUBF[14:0] register for the second time. Note that NRST cannot be triggered during above process.

5.5 The shift operation of the RTC on the subsecond causes the current

wake-up time is inaccurate

Description

When the RTC is configured to periodic wake up, performing the shift operation for subseconds before triggering the periodic wake-up will cause the current wake-up time is inaccurate, and the subsequent wake-up time will be normal.

Resolution

None

5.6 RTC_DATE register lock

Description

- Before the system software reset, the RTC_DATE register is not read after reading the RTC_SUBS or RTC_TSH shadow register, and the RTC_DATE register will restores the default value after the system software resets and initializes the RTC without configuration or reads the RTC_DATE register;
- 2. When reading the calendar, after reading the RTC_SUBS or RTC_TSH shadow register, the value of the RTC_DATE register remains unchanged;

Resolution

- 1. Read the RTC_DATE register before initializing the RTC;
- 2. After reading the RTC_SUBS or RTC_TSH shadow register, read the RTC_DATE register;



6 GPIO and AFIO


6.1 IO appeared burr during power-on

Description

When the MCU is powered on, some IOs will have burrs appeared.

Resolution


When IO is used as input, the burr has no effect on MCU; When IO is used as output, 2000hm resistor and 0.1uF capacitor are applied for filtering.







7 Marking information





8 Version history

Date	Version	Remark
2023.5.16	V1.0.0	Initial release



9 Notice

This document is the exclusive property of Nations Technologies Inc. (Hereinafter referred to as NATIONS). This document, and the product of NATIONS described herein (Hereinafter referred to as the Product) are owned by NATIONS under the laws and treaties of the People's Republic of China and other applicable jurisdictions worldwide.

NATIONS does not grant any license under its patents, copyrights, trademarks, or other intellectual property rights. Names and brands of third party may be mentioned or referred thereto (if any) for identification purposes only.

NATIONS reserves the right to make changes, corrections, enhancements, modifications, and improvements to this document at any time without notice. Please contact NATIONS and obtain the latest version of this document before placing orders.

Although NATIONS has attempted to provide accurate and reliable information, NATIONS assumes no responsibility for the accuracy and reliability of this document.

It is the responsibility of the user of this document to properly design, program, and test the functionality and safety of any application made of this information and any resulting product. In no event shall NATIONS be liable for any direct, indirect, incidental, special, exemplary, or consequential damages arising in any way out of the use of this document or the Product.

NATIONS Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at user's risk. User shall indemnify NATIONS and hold NATIONS harmless from and against all claims, costs, damages, and other liabilities, arising from or related to any customer's Insecure Usage.

Any express or implied warranty with regard to this document or the Product, including, but not limited to, the warranties of merchantability, fitness for a particular purpose and non-infringement are disclaimed to the fullest extent permitted by law.

Unless otherwise explicitly permitted by NATIONS, anyone may not use, duplicate, modify, transcribe or otherwise distribute this document for any purposes, in whole or in part.